CARRO

150 Point Inspection Checklist

Toyota Corolla Altis 1.6 Cvt Grey

Report ID: GRb4xYRnbB-1618213816

Road Test

Item	Value
Engine Starts Properly	Pass
Engine Idles Properly	Pass
Engine Noise	Pass
Engine Acceleration	Pass
Clutch Operates Properly	N/A

Item	Value
Brakes	Pass
Gauges Operate Properly	Pass
Gear Box	Pass
Suspension	Pass

Exterior

Item	Value
No Evidence Of Flood Damage	Pass
Body Panel Inspection	Pass
Front Bumper	Fail
Front Bonnet	Pass
Front Fender (Left)	Fail
Front Doors (Left)	Fail
Rear Doors (Left)	Fail
Rear Fender / Quaterpanel (Left)	Fail
Rear Bonnet	Pass
Rear Bumper	Fail
Rear Fender / Quaterpanel (Right)	Fail
Rear Doors (Right)	Fail
Front Doors (Right)	Fail
Front Fender (Right)	Pass
Front Windscreen	Fail
Rear Windscreen	Pass

Item	Value
Front Window (Left)	Pass
Rear Window (Left)	Pass
Rear Quarter Window (Left)	Pass
Front Window (Right)	Pass
Rear Window (Right)	Pass
Rear Quarter Window (Right)	Pass
Left Side Mirror	Pass
Right Side Mirror	Pass
Front End Exterior Lights (Left)	Pass
Rear End Exterior Lights (Left)	Pass
Front End Exterior Lights (Right)	Pass
Rear End Exterior Lights (Right)	Pass
Side Exterior Lights	Pass
Hazard Lights	Pass
Side Skirt (Left)	Pass
Side Skirt (Right)	Pass

Interior

Item	Value
Airbags	3
Safety Belts	Pass
Radio / Cassette / Cd/Dvd Player	Pass
Antenna	Pass
Alarm / Theft Deterrent System	Pass
Speakers	Pass
Reverse Camera	Pass
Air Conditioning System	Pass
Air Conditioning Switch Panel	Pass
Center Armrest / Console	Pass
Front Aircon Vents	Pass
Rear Aircon Vents	N/A
Clock	Pass
Tilt / Telescopic Steering Wheel	Pass
Steering Wheel Controls	Pass
Steering Wheel Condition	Pass
Horn	Pass
Indicator Light	Pass
Warning Light	Pass
Tripmeter And Odometer	Pass
Windscreen Wipers Switch	Pass
Rear Window Wiper Switch	N/A
Paddle Shifters	N/A
Interior Courtesy, Dome & Map Lights	Pass
Outside Rear View Mirrors	Pass
Ashtrays	N/A
Gear Knob	Pass
Handbrake / Footbrake Lever	Pass
Sun Visors, Vanity Mirror & Light	Pass

Item	Value
Dashboard	Pass
Dashboard Drawer	Pass
Interior Carpet	Pass
Floor Mats	Fail
Front Door Panel (Left)	Pass
Rear Door Panel (Left)	Pass
Front Door Panel (Right)	Pass
Rear Door Panel (Right)	Pass
Headlining	Pass
Front Seat	Pass
Rear Seat	Pass
Seat & Head Restraint Adjustment	Pass
Folding Seats	N/A
Heated Seats	N/A
Cooled Seats	N/A
Sunroof / Moonroof	N/A
Convertible Top	N/A
Door Handles	Pass
Push Start Button System	Pass
Central Locking System	Pass
Power Window Controls	Pass
Remote Boot Release	Pass
Fuel Cap Release	Pass
Luggage Compartment Trim & Cargo Net	Pass
Luggage Compartment Light	Pass
Luggage Board	Pass
Parcel Shelf / Speaker Board / Tonneau Cover	Pass
Jack & Tool Kit	Pass
Spare Tyre	Pass

Underbody

Item	Value
Exhaust System	Pass
4X4 Operation	N/A
Front Tyre (Left)	Pass
Rear Tyre (Left)	Pass
Front Tyre (Right)	Pass
Rear Tyre (Right)	Pass
Rims	Pass

Item	Value
Wheel Covers & Center Caps	Pass
Rack And Pinion, Linkage & Boots	Pass
Control Arms & Ball Joints	Pass
Tie Rods & Idler Arm	Pass
Sway Bars, Links & Bushings	Pass
Wheel Alignment	Pass

Under The Hood

Item	Value
Engine Oil	Pass
Coolant	Pass
Coolant Tank	Pass
Radiator	Pass
Brake Fluid	Pass
Power Steering Fluid	N/A
Air Conditioning Parts	Pass
Hoses,Lines & Fittings	Pass
Belting	Pass

Item	Value
Wiring	Pass
Engine & Transmission Mounting	Pass
Engine Cover	Pass
Transmission Fluid	Pass
Battery	Pass
Engine Oil Leaks	Pass
Transmission Fluid Leaks	Pass
Wiper Blades Front & Rear	Pass

View full listing at carro.sg/q/EKO9RW