



## 150 Point Inspection Checklist

Mitsubishi Space Star 1.2 Cvt

Report ID: YqaQWr27dn-1624599639

## Road Test

Item	Value	Item	Value
Engine Starts Properly	Pass	Brakes	Pass
Engine Idles Properly	Pass	Gauges Operate Properly	Pass
Engine Noise	Pass	Gear Box	Pass
Engine Acceleration	Pass	Suspension	Pass
Clutch Operates Properly	N/A		

## Exterior

Item	Value	Item	Value
No Evidence Of Flood Damage	Pass	Front Window (Left)	Pass
Body Panel Inspection	Pass	Rear Window (Left)	Pass
Front Bumper	Pass	Rear Quarter Window (Left)	Pass
Front Bonnet	Pass	Front Window (Right)	Pass
Front Fender (Left)	Pass	Rear Window (Right)	Pass
Front Doors (Left)	Pass	Rear Quarter Window (Right)	Pass
Rear Doors (Left)	Pass	Left Side Mirror	Pass
Rear Fender / Quaterpanel (Left)	Pass	Right Side Mirror	Pass
Rear Bonnet	Pass	Front End Exterior Lights (Left)	Pass
Rear Bumper	Pass	Rear End Exterior Lights (Left)	Pass
Rear Fender / Quaterpanel (Right)	Pass	Front End Exterior Lights (Right)	Pass
Rear Doors (Right)	Pass	Rear End Exterior Lights (Right)	Pass
Front Doors (Right)	Pass	Side Exterior Lights	Pass
Front Fender (Right)	Pass	Hazard Lights	Pass
Front Windscreen	Pass	Side Skirt (Left)	Pass
Rear Windscreen	Pass	Side Skirt (Right)	Pass

# Interior

Item	Value	Item	Value
Airbags	Pass	Dashboard	Pass
Safety Belts	Pass	Dashboard Drawer	Pass
Radio / Cassette / Cd/Dvd Player	Pass	Interior Carpet	Pass
Antenna	Pass	Floor Mats	Pass
Alarm / Theft Deterrent System	Pass	Front Door Panel (Left)	Pass
Speakers	Pass	Rear Door Panel (Left)	Pass
Reverse Camera	Pass	Front Door Panel (Right)	Pass
Air Conditioning System	Pass	Rear Door Panel (Right)	Pass
Air Conditioning Switch Panel	Pass	Headlining	Pass
Center Armrest / Console	Pass	Front Seat	Pass
Front Aircon Vents	Pass	Rear Seat	Pass
Rear Aircon Vents	Pass	Seat & Head Restraint Adjustment	Pass
Clock	Pass	Folding Seats	Pass
Tilt / Telescopic Steering Wheel	Pass	Heated Seats	N/A
Steering Wheel Controls	Pass	Cooled Seats	N/A
Steering Wheel Condition	Pass	Sunroof / Moonroof	N/A
Horn	Pass	Convertible Top	N/A
Indicator Light	Pass	Door Handles	Pass
Warning Light	Pass	Push Start Button System	Pass
Tripmeter And Odometer	Pass	Central Locking System	Pass
Windscreen Wipers Switch	Pass	Power Window Controls	Pass
Rear Window Wiper Switch	Pass	Remote Boot Release	Pass
Paddle Shifters	N/A	Fuel Cap Release	Pass
Interior Courtesy, Dome & Map Lights	Pass	Luggage Compartment Trim & Cargo Net	Pass
Outside Rear View Mirrors	Pass	Luggage Compartment Light	Pass
Ashtrays	N/A	Luggage Board	Pass
Gear Knob	Pass	Parcel Shelf / Speaker Board / Tonneau Cover	Pass
Handbrake / Footbrake Lever	Pass	Jack & Tool Kit	Pass
Sun Visors, Vanity Mirror & Light	Pass	Spare Tyre	N/A

# Underbody

Item	Value
Exhaust System	Pass
4X4 Operation	N/A
Front Tyre (Left)	Pass
Rear Tyre (Left)	Pass
Front Tyre (Right)	Pass
Rear Tyre (Right)	Pass
Rims	Pass

Item	Value
Wheel Covers & Center Caps	Pass
Rack And Pinion, Linkage & Boots	Pass
Control Arms & Ball Joints	Pass
Tie Rods & Idler Arm	Pass
Sway Bars, Links & Bushings	Pass
Wheel Alignment	Pass

# Under The Hood

Item	Value
Engine Oil	Pass
Coolant	Pass
Coolant Tank	Pass
Radiator	Pass
Brake Fluid	Pass
Power Steering Fluid	N/A
Air Conditioning Parts	Pass
Hoses, Lines & Fittings	Pass
Belting	Pass

Item	Value
Wiring	Pass
Engine & Transmission Mounting	Pass
Engine Cover	N/A
Transmission Fluid	Pass
Battery	Pass
Engine Oil Leaks	Pass
Transmission Fluid Leaks	Pass
Wiper Blades Front & Rear	Pass

View full listing at [carro.sg/q/DR1WLN](https://carro.sg/q/DR1WLN)