



123 Point Inspection Checklist

HYUNDAI I40 I40 GLS

Report ID: jneg5Kokbw-1638959089

Car Information

Item	Value	Item	Value
Plate No. (Sell with/Sell without).	Sell With	Registration Date	2015-01-22
Brand	HYUNDAI	Engine No.	G4NCDU910240
Model	I40	Chassis No.	KMHLC41DM EU049365
Sub Model	I40 GLS	Engine Capacity	2000
Color	SILVER	Mileage	89686
Manufactured Year	2014	Seat Number	5
Transmission	Automatic	No. of previous Owner	1
Fuel type	Petrol	Service Book/Sticker	Yes
Registration Card	New	AP	N/A
Registration Type	Private		

Exterior

Item	Value	Item	Value
No Evidence Of Flood Damage	Pass	Hood Release Mechanism	Pass
No Evidence Of Major Accident	Pass	Hood Hinges, Prod Rod / Gas Struts	Pass
Body Panel Inspection	Pass	Door Hinges Operate Properly	Pass
Front Bumper	Pass	Grille Inspection	Pass
Front Bonnet	Pass	Windscreen	Pass
Front Fender (Left)	Pass	Side Glass	Pass
Front Doors (Left)	Pass	Rear Window / Tailgate Glass	Pass
Rear Doors (Left)	Pass	Wiper Blades Front & Rear	Pass
Rear Fender / Quarterpanel (Left)	Pass	Left Side Mirror	Pass
Rear Bonnet	Pass	Right Side Mirror	Pass
Rear Bumper	Pass	Auto Folding Mirror	Pass
Rear Fender / Quarterpanel (Right)	Pass	Front End Exterior Lights	Fail
Rear Doors (Right)	Pass	Rear End Exterior Lights	Pass
Front Doors (Right)	Pass	Side Exterior Lights	Fail
Front Fender (Right)	Pass	Hazard Lights	Pass
Doors Inspection / Alignment	Pass		

Interior

Item	Value	Item	Value
Airbags	2	Sun Visors, Vanity Mirror & Light	Pass
Safety Belts	Pass	Dashboard	Pass
Radio / Cassette / Cd/Dvd Player	Pass	Dashboard Drawer	Pass
Antenna	Pass	Interior Carpet	Pass
Alarm / Theft Deterrent System	Pass	Floor Mats	Pass
Speakers	Pass	Door Trim & Door Panels	Fail
Reverse Camera	N/A	Headlining	Pass
Air Conditioning System	Pass	Front Seat	Fail
Air Conditioning Switch Panel	Pass	Rear Seat	Fail
Center Armrest / Console	Pass	Seat & Head Restraint Adjustment	Fail
Front Aircon Vents	Fail	Folding Seats	Pass
Rear Aircon Vents	Fail	Heated Seats	N/A
Clock	Pass	Cooled Seats	N/A
Tilt / Telescopic Steering Wheel	Pass	Sunroof / Moonroof	Pass
Steering Wheel Controls	Pass	Convertible Top	N/A
Steering Wheel Condition	Fail	Door Handles	Pass
Horn	Pass	Push Start Button System	Pass
Indicator Light	Pass	Central Locking System	Pass
Warning Light	Pass	Power Window Controls	Pass
Tripmeter And Odometer	Pass	Remote Boot Release	Pass
Windscreen Wipers Switch	Pass	Fuel Cap Release	Pass
Rear Window Wiper Switch	Pass	Luggage Compartment Trim & Cargo Net	Pass
Paddle Shifters	N/A	Luggage Compartment Light	Pass
Interior Courtesy, Dome & Map Lights	Pass	Luggage Board	Pass
Outside Rear View Mirrors	N/A	Parcel Shelf / Speaker Board / Tonneau Cover	Pass
Ashtrays	Pass	Jack & Tool Kit	Pass
Gear Knob	Pass	Spare Tyre	Pass
Handbrake / Footbrake Lever	Pass		

Underbody

Item	Value	Item	Value
Exhaust System	Pass	Wheel Covers & Center Caps	Pass
4X4 Operation	Pass	Rack And Pinion, Linkage & Boots	Pass
Front Tyre (Left)	Pass	Control Arms & Ball Joints	Pass
Rear Tyre (Left)	Pass	Tie Rods & Idler Arm	Pass
Front Tyre (Right)	Pass	Sway Bars, Links & Bushings	Pass
Rear Tyre (Right)	Pass	Wheel Alignment	Pass
Rims	Fail		

Under The Hood

Item	Value	Item	Value
Engine Oil	Pass	Belting	Pass
Coolant	Pass	Wiring	Pass
Coolant Tank	Pass	Engine & Transmission Mounting	Pass
Radiator	Pass	Engine Cover	Pass
Brake Fluid	Pass	Transmission Fluid	Pass
Power Steering Fluid	Pass	Battery	Pass
Air Conditioning Parts	Pass	Engine Oil Leaks	Pass
Hoses, Lines & Fittings	Pass	Transmission Fluid Leaks	Pass

Road Test

Item	Value	Item	Value
Engine Starts Properly	Pass	Brakes	Pass
Engine Idles Properly	Pass	Gauges Operate Properly	Pass
Engine Noise	Pass	Gear Box	Pass
Engine Acceleration	Pass	Suspension	Pass
Clutch Operates Properly	N/A		

Other information

Item	Value	Item	Value
Inspection Place	In House	B2/B5 Forms	No
Location	RETAIL (Puchong) PRE-LISITNG	Remark	
E-Hailing	No		

View full listing at mytukar.com/q/GP26WM