



123 Point Inspection Checklist
VOLKSWAGEN PASSAT PASSAT
Report ID: w9aAnzq7bv-1641445576

Car Information

Item	Value
Plate No. (Sell with/Sell without).	Sell With
Brand	VOLKSWAGE N
Model	PASSAT
Sub Model	PASSAT
Color	SILVER
Manufactured Year	2018
Transmission	Automatic
Fuel type	Petrol
Registration Card	New
Registration Type	Private

Item	Value
Registration Date	2022-01-05
Engine No.	-
Chassis No.	-
Engine Capacity	1800
Mileage	45886
Seat Number	5
No. of previous Owner	1
Service Book/Sticker	No
AP	N/A

Exterior

Item	Value
No Evidence Of Flood Damage	Pass
No Evidence Of Major Accident	Pass
Body Panel Inspection	Pass
Front Bumper	Pass
Front Bonnet	Pass
Front Fender (Left)	Pass
Front Doors (Left)	Pass
Rear Doors (Left)	Pass
Rear Fender / Quaterpanel (Left)	Pass
Rear Bonnet	Pass
Rear Bumper	Pass
Rear Fender / Quaterpanel (Right)	Pass
Rear Doors (Right)	Pass
Front Doors (Right)	Pass
Front Fender (Right)	Pass
Doors Inspection / Alignment	Pass

Item	Value
Hood Release Mechanism	Pass
Hood Hinges, Prod Rod / Gas Struts	Pass
Door Hinges Operate Properly	Pass
Grille Inspection	Pass
Windscreen	Pass
Side Glass	Pass
Rear Window / Tailgate Glass	Pass
Wiper Blades Front & Rear	Pass
Left Side Mirror	Pass
Right Side Mirror	Pass
Auto Folding Mirror	Pass
Front End Exterior Lights	Fail
Rear End Exterior Lights	Pass
Side Exterior Lights	Pass
Hazard Lights	Pass

Interior

Item	Value	Item	Value
Airbags	6	Sun Visors, Vanity Mirror & Light	Pass
Safety Belts	Pass	Dashboard	Pass
Radio / Cassette / Cd/Dvd Player	Pass	Dashboard Drawer	Pass
Antenna	Pass	Interior Carpet	Pass
Alarm / Theft Deterrent System	Pass	Floor Mats	Pass
Speakers	Pass	Door Trim & Door Panels	Pass
Reverse Camera	Pass	Headlining	Pass
Air Conditioning System	Pass	Front Seat	Pass
Air Conditioning Switch Panel	Pass	Rear Seat	Pass
Center Armrest / Console	Pass	Seat & Head Restraint Adjustment	Pass
Front Aircon Vents	Pass	Folding Seats	Pass
Rear Aircon Vents	Pass	Heated Seats	N/A
Clock	Pass	Cooled Seats	N/A
Tilt / Telescopic Steering Wheel	Pass	Sunroof / Moonroof	N/A
Steering Wheel Controls	Pass	Convertible Top	N/A
Steering Wheel Condition	Pass	Door Handles	Pass
Horn	Pass	Push Start Button System	Pass
Indicator Light	Pass	Central Locking System	Pass
Warning Light	Pass	Power Window Controls	Pass
Tripmeter And Odometer	Pass	Remote Boot Release	Pass
Windscreen Wipers Switch	Pass	Fuel Cap Release	Pass
Rear Window Wiper Switch	N/A	Luggage Compartment Trim & Cargo Net	Pass
Paddle Shifters	N/A	Luggage Compartment Light	Pass
Interior Courtesy, Dome & Map Lights	Pass	Luggage Board	Pass
Outside Rear View Mirrors	N/A	Parcel Shelf / Speaker Board / Tonneau Cover	Pass
Ashtrays	Pass	Jack & Tool Kit	Pass
Gear Knob	Pass	Spare Tyre	Pass
Handbrake / Footbrake Lever	Pass		

Underbody

Item	Value	Item	Value
Exhaust System	Pass	Wheel Covers & Center Caps	Pass
4X4 Operation	N/A	Rack And Pinion, Linkage & Boots	Pass
Front Tyre (Left)	Pass	Control Arms & Ball Joints	Pass
Rear Tyre (Left)	Pass	Tie Rods & Idler Arm	Pass
Front Tyre (Right)	Pass	Sway Bars, Links & Bushings	Pass
Rear Tyre (Right)	Pass	Wheel Alignment	Pass
Rims	Pass		

Under The Hood

Item	Value	Item	Value
Engine Oil	Pass	Belting	Pass
Coolant	Pass	Wiring	Pass
Coolant Tank	Pass	Engine & Transmission Mounting	Pass
Radiator	Pass	Engine Cover	Pass
Brake Fluid	Pass	Transmission Fluid	Pass
Power Steering Fluid	N/A	Battery	Pass
Air Conditioning Parts	Pass	Engine Oil Leaks	Fail
Hoses, Lines & Fittings	Pass	Transmission Fluid Leaks	Pass

Road Test

Item	Value	Item	Value
Engine Starts Properly	Pass	Brakes	Pass
Engine Idles Properly	Pass	Gauges Operate Properly	Pass
Engine Noise	Pass	Gear Box	Pass
Engine Acceleration	Pass	Suspension	Fail
Clutch Operates Properly	N/A		

Other information

Item	Value	Item	Value
Inspection Place	In House	B2/B5 Forms	No
Location	RETAIL (Puchong) PRE-LISITNG	Remark	
E-Hailing	No		

View full listing at mytukar.com/q/EQ2168